

#08



WORKFORCE REQUEST

Attention: Dispatch Local 110

RSAP Accepted: ☒ YES ☐ NO

Job Steward: TBD

Order Date: 18-Aug-26

Project Description: TransAlta - Keephills 3 Turnaround

Journeyman's Rate of Pay: \$52.74

Work Agreement: NMA

Order Time: 13:00

Trade	# Workers Required	Skill Level	Orientation Date & Time	Work Start Date & Time	Work Schedule	Job Duration	Shift
Insulator	5	JM	Aug 31, 2026 at 9am	Sept 1, 2026 @ 7am	5 x 10+	1 weeks +	Days
Insulator	2	APP2 or 3	Aug 28, 2026 at 9am	Sept 1, 2026 @ 7am	5 x 10+	1 weeks +	Days
Insulator	2	App 1	Aug 28, 2026 at 9am	Sept 1, 2026 @ 7am	5 x 10+	1 weeks +	Days

Special Instructions: Must be physically fit, kneel, crouch, work at heights, able to wear sealed eye protection, must be able to wear RPE, able to communicate in english (spoken & written), supply own hand tools as per Union Collective Agreement which will be inspected upon arrival at site, able to perform heavy manual lifting, climb stairs & ladders. CSTS 09 or CSTS 09 Upgrade and WHIMS 2015 are required. Clean shaven policy. Must have industrial experience

No Camp, No Travel, and No Sub. - Mileage Paid

Pre Access A&D Testing required - please book through CANN-AMM 1-800-440-0023 - IND12583

Name Hires Requested:


Recalls:

Referrals to be sent to:

Philippe Malouin -

Contact company Safety Representative for Orientation Information:
Randy Roberts

Dispatch to Keephills Generating Station



Driving directions to Keephills from Edmonton:

Highway 16

1. Take Highway 16 (Yellowhead) West
2. Turn Left (South) on Highway 770
3. Turn Right (West) on Highway 627
4. Continue on Highway 627 West
5. Keephills will be on your left

Highway 627

1. Take Highway 627 West
2. Continue past Highway 770
3. Keephills will be on your left

Call-In Number:

Shift Start Times:

Please bring with you:

Day Shift: 7:00 - 17:00

- Steel Toe Footware
- Tools
- Other PPE will be provided

- Prescription PPE as required
- Training Certifications
- Bank Information (Void Check)